

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 28

Township: 8 North



Range: 2 West

Corner ID: Van Bu K-19

Monument Description & Remarks: MAG nail in center of Harmony Road. Survey Sign 3ft above ground at pt (C).

References On File: Bledsoe survey, Hinkle's (2005), on file in Surveyor Office & Recorder Office (IN# 2005010419).

RECOVERY TIE DRAWING
Field Book 36 Page No. 31



- A - MAG nail in center of Harmony Rd.
- B - N 86° W 24.95' to 5/8" Rebar with cap.
- C - N 85° W 33.29' to MAG nail in Survey Sign on 9" PWP.
- D - N 40° E 91.55' to MAG nail in 13" PWP.
- E - S 76° E 22.41' to Fence Post.

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Sections 2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 28th day of November 2005.

Kevin P. Enright



Administered by the Monroe County Surveyor's Board

Date: 10/24/06

